



NATIONAL  
ENVIRONMENTAL  
TESTING, INC.

SEP 29 1998

Indianapolis Division  
6964 Hillside Ct.  
Indianapolis, IN 46250  
Tel: (317) 842-4261  
Fax: (317) 842-4286

## ANALYTICAL REPORT

Mr. Richard Tyler  
MILBANK MANUFACTURING INC  
1400 E. HAVENS ST.  
KOKOMO, IN 56901-3188

09/24/1998

NET Job Number: 98.06460  
Page 1 of 3

Enclosed are the Analytical Results for the following samples submitted to NET, Inc. Indianapolis Division for analysis:

Project Description: TWICE WEEKLY WASTEWATER

Sample Number	Sample Description	Date Taken	Date Received
218617	OUTFALL 001	09/15/1998	09/17/1998

National Environmental Testing, Inc. certifies that the analytical results contained herein apply only to the specific samples analyzed.

Reproduction of this analytical report is permitted only in its entirety.

Project Representative

MIL0003075



NATIONAL  
ENVIRONMENTAL  
TESTING, INC.

SEP 29 1998

Indianapolis Division  
6964 Hillsdale Ct.  
Indianapolis, IN 46250  
Tel: (317) 842-4261  
Fax: (317) 842-4286

## ANALYTICAL REPORT

Mr. Richard Tyler  
MILBANK MANUFACTURING INC  
1400 E. HAVENS ST.  
KOKOMO, IN 56901-3188

09/24/1998

Job No.: 98.06460

Page 2 of 3

Date Received: 09/17/1998

Job Description: TWICE WEEKLY WASTEWATER

Sample Number / Sample I.D.			Sample Date/	Analyst &		Reporting
Parameters	Result	Flag	Units	Date Analyzed	Method	Limit
218617	OUTFALL 001		09/15/1998			
Iron, ICP	1.4		mg/L	psc / 09/18/1998	EPA 200.7	<0.10
Lead, ICP	<0.080		mg/L	psc / 09/18/1998	EPA 200.7	<0.080
Silver, ICP	<0.020		mg/L	psc / 09/18/1998	EPA 200.7	<0.020
Zinc, ICP	0.084		mg/L	psc / 09/18/1998	EPA 200.7	<0.020

MIL0003076



NATIONAL  
ENVIRONMENTAL  
TESTING, INC.

SEP 29 1998

Indianapolis Division  
6964 Hillsdale Ct.  
Indianapolis, IN 46250  
Tel: (317) 842-4261  
Fax: (317) 842-4286

## FIELD REPORT

JOB #: 98.06460  
CLIENT: MILBANK MFG.  
PROJECT: TWICE WEEKLY WASTEWATER  
DATE: 9/15/98  
SAMPLER(S): CAB

An ISCO model 3710 auto sampler was used in the composite mode of operation. The sampler was equipped with a plastic composite jug, tygon suction line, battery, ice, and strainer.

All reusable equipment is decontaminated withalconox, tap water, 5% nitric acid, and deionized water. New tygon suction tubing was used for the sampler. A stainless steel strainer was also used for the sampling event.

The sampler was set to take a sample every 30 minutes for 8 hours.

Monitoring start 07:30 on 9/15/98  
Monitoring end 15:00 on 9/15/98

The composite sample was clear.

Notes: Samples were preserved, in the field, in the appropriate containers with any required preservative.

MIL0003077



COMPANY M. L. Bank Mfg.  
ADDRESS 1400 E. Haverly St  
PHONE \_\_\_\_\_ FAX \_\_\_\_\_  
PROJECT NAME/LOCATION Tennis weekly  
PROJECT NUMBER \_\_\_\_\_  
PROJECT MANAGER Richard Tyler

NET QUOTE NO. 78.0060

SEP 29 1998

(PRINT NAME)

SIGNATURE

## ANALYSES

To assist us in selecting the proper method

Is this work being conducted for regulatory enforcement action? Yes \_\_\_\_\_ No \_\_\_\_\_

Which regulations apply: RCRA \_\_\_\_\_ NPDES Wastewater \_\_\_\_\_  
UST \_\_\_\_\_ Drinking Water \_\_\_\_\_  
Other \_\_\_\_\_ None \_\_\_\_\_

## COMMENTS

[illegible]

TEMPERATURE UPON RECEIPT: 7.5°C  
Bottles supplied by NET? YES/NO

DATE \_\_\_\_\_

RECEIVED FOR NET BY: *Joshua S. Oath* 11:00  
9/17/09

REMARKS:

**MIL0003078**